

eQart®

BY



eQart software release 2.1.1

What's new in version 2.1.1

Update 2.1.1 is the first update post eQart brain 2.0 release. This update focuses on fixing many minor bugs related to this launch. The update also focuses on fixing some rare bugs in the mission planner and mapping as well as some code optimization to make the eQart more responsive.

What's fixed?

- Fixed several bugs that caused problems of detecting an RFID-station if the breaks were initiated.
- Fixed a bug that would mess with the cart direction if the eQart was on an RFID-station and the break was triggered.
- Fixed a bug that caused the map to be created incorrectly if an obstacle triggered the safety while the eQart was in an intersection.
- Fixed a problem with mapping a circular route where the eQart would not switch direction when coming back to the start station but instead keep going in the loop, thus continuing to map indefinitely.
- Fixed a bug where the eQart would display incorrect LED colors while on a mission.
- Updated the application to work better with Android 9.0 OS
- Fixed some UI bugs in the mission planner
- Fixed a bug that appeared when an emergency stop was triggered in mapping where the eQart would switch directions quickly, giving the eQarts LED the impression of a disco.