

# eQart®

BY

 FLEXQUBE®

## eQart software release 2.1.2

### What's new in version 2.1.2

Update 2.1.2 introduces two new features.

- The option for eQarts equipped with ultrasonic sensors to have all sensors pointing in the same direction. This is enabled in settings.
- A new feature in the rotation block in the mission planner. When selecting 180 degrees rotation, the application will also give you an option to change driving direction, by selecting this option the eQart will switch direction after the rotation, and the navigation will work as expected.

### What's fixed?

- Fixed a bug regarding network registration and binding that would randomly crash the application.