

eQart®

BY

 FLEXQUBE®

eQart software release 2.3.2

Firmware updates

- Improved hardware diagnostics
- Improved line detection in high brightness environment
- Improved junction detection
- Fixed interlocking issue

Application updates

- New Navigation block in mission planner
- Mission can now be started from any station
- 90-degree rotation block now have change direction functionality
- RFID tag-number can now be changed in saved maps
- FlexButton naming error fixed